


Support bracket for X85 drive units Type H



Technical bulletin from FlexLink

5393EN-1

New bracket uses drive unit's T-slot for firm support



For X85 drive units Type H

A new type of support bracket uses the T-slot of the direct drive units. This results in a rigid support at the drive unit, instead of just supporting the conveyor beam next to the drive unit. The new support is primarily intended for X85 direct drive unit Type H without slip clutch.

Note.

The recommended support solution for direct drive units with slip clutch is to connect the support beam to the adapter plate.

Important features

- Support directly at the drive unit
- Sturdy and reliable screw– slot nut connection
- Easy assembly

Support bracket for drive unit

