




PRE-REQUISITES


Recommended tools

See slide rail assembly instruction











XLAHX 4x7

SAFETY





**WARNING**  
The system must not be operated without safety equipment properly mounted.





**WARNING**  
At installation, maintenance and service, make sure the motor is shut off.

PRODUCTS



XBCCX 300A85




XBCCX 300A180



XBCCX 300A300




1. The sub-frames must be removed for feeding the conveyor chain into the line.
2. Clamp the chain to the beam profile. Use the FlexLink chain tool to remove a steel pin from the chain, so that two links are separated.
3. Remove excess links and use the chain tool to put the chain back together again.



**Mounting slide rail**

**XBCCX 300A85**

5115295



# ASSEMBLY INSTRUCTION

## Beam section for chain installation

XBCCX 300A85  
XBCCX 300A180  
XBCCX 300A300

**XBCCX 300A180 / XBCCX 300A300**

